

UNITED STATES PATENT AND TRADEMARK OFFICE

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OPPICE
WASHINGTON, D.C. 20231
www.uspio.gov

Bib Data Sheet

CONFIRMATION NO. 6341

SERIAL NUMBE 10/043,367	FILING DATE 01/09/2002 RULE	CLASS 239	GROUP ART 3752	OUP ART UNIT 3752		ATTORNEY DOCKET NO. 10541-640		
** CONTINUING DATA **********************************								
Foreign Priority claimed 35 USC 119 (a-d) conditi met Verified and Acknowledged	Allowation 6/11/04	STATE OR COUNTRY MI	SHEETS DRAWING 5	TOTA CLAII 29	MS	INDEPENDENT CLAIMS 2		
ADDRESS Steven L. Oberholt BRINKS HOFER G P.O. Box 10395 Chicago ,IL 60610	SILSON & LIONE							
TITLE Fuel injector nozzle assembly								
RECEIVED N	EES: Authority has been givo. o to charge/creo. for following:	Authority has been given in Paper to charge/credit DEPOSIT ACCOUNT for following:			☐ All Fees ☐ 1.16 Fees (Filing) ☐ 1.17 Fees (Processing Ext. of time) ☐ 1.18 Fees (Issue) ☐ Other ☐ Credit			

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:				
BLACK BORDERS				
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES				
☐ FADED TEXT OR DRAWING				
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING				
☐ SKEWED/SLANTED IMAGES				
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS				
☐ GRAY SCALE DOCUMENTS				
☐ LINES OR MARKS ON ORIGINAL DOCUMENT				
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY				
П отнер.				

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.